


## 4 Conductor Wiring Instructions



For standard series (humbucking) wiring, connect red and green and tape off — white is hot, black/shield is ground.

For single-coil mode — red and green go to ground.